Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020038-4

File Insp. Sect

~~SECRET~~ CONFIDENTIAL

14-816

Chief, Procurement Division, LO 18 March 1954

Chief, Engineering Division, OC

RC-6 Units, Repair of: Re: RSC-148-UNV
51-3178

1. Re your memorandum of 19 February 1954 concerning the expired warranty on 19 each RC-6 units previously rejected by T&E Section, OC, the following action has been taken:

a. 18 units have been reconditioned.

b. 1 unit serial #3178 requires the following parts to repair and recondition it.

1 each - Transformer, RF, low frequency adjustable core, Part #424B158 symbol T-3.

1 each - Transformer, I.F. output, without case, Part #424B121 symbol T-9.

1 each - Condenser, variable, BFO control, Part #419B102 symbol C-49. (1.7-8.7 mmf shorting type).

1 each - Crystal, calibrator, 500 kc Part #446A103 symbol Y2.

1 each - Earset, Telex, without holder and cord.

2. Unit mentioned above is in custody of T&E Section, [redacted], until repair parts become available. All others have been returned to the Receiving Section. 25X1 25X1

[redacted] 25X1

OC-E/JFS/HBM/ljd

Distribution:
1 - Courtesy
1 - Eng.
1 - Eng/C&ERB
1 - R&D Ext. Proj.
1 - Chrono
1 - T&E Ref. No. 01804

[redacted] 25X1

~~SECRET~~ CONFIDENTIAL

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020038-4